# Maryland Historical Trust

Maryland Inventory of Historic Properties Number Name: Light Love Love Love Love Love Love Love Love	e Maryland S	State Hig	hway ility d	Admi eterm	inatio	ns in	l
MARYLAND HIS Eligibility Recommended X		RUST gibility N	lot Rec	comm	ended		
Criteria:ABCD Consideration	ıs:A]	BC _	_D _	_E _	F	_G_	_None
Comments:						-	
Reviewer, OPS:Anne E. Bruder		Dat	e:3 <i>I</i>	April 2	2001_		
Reviewer, NR Program: Peter E. Kurtze		Dat	e:3	April	2001		-

Maryland Inventory of Historic Properties Historic Bridge Inventory Maryland State Highway Administration Maryland Historical Trust

Maryland Historical Trust
SHA Bridge No. M 120 Name: Griffith Road over Hawlings River
Location: Street/Road Name and Number: Griffith Road
City/Town: Brookville Vicinity X
County: Montgomery
Ownership:State_X_County_MunicipalOther
This bridge projects over:RoadRailway_X_WaterLand
Is the bridge located within a designated district:yes_X_no
_NR listed district_NR determined eligible district _locally designated_other Name of District
Bridge Type:
Timber BridgeBeam BridgeTruss-CoveredTrestleTimber-and-Concrete
_Stone Arch
_Metal Truss
_Movable Bridge _Swing _Bascule Single Leaf_Bascule Multiple Leaf _Vertical Lift_Retractile_Pontoon
Metal GirderRolled GirderRolled Girder Concrete EncasedPlate GirderPlate Girder Concrete Encased
_Metal Suspension
_Metal Arch
_Metal Cantilever
_X_Concrete Arch _Concrete Slab_Concrete Beam _Rigid Frame
_Other Type Name

# **Describe Setting:**

Bridge M 120 carries Griffith Road over Hawlings River in Montgomery County. Griffith Road runs east-west over the north branch of the Hawlings River. The area immediately adjacent to the bridge has little residential development.

### **Describe Superstructure and Substructure:**

Bridge M 120 is a single span filled concrete arch bridge. The length of the bridge is 25 feet 4 inches with a clear span of 23 feet 3 inches. The bridge has a rise of approximately 5 feet 7 inches from springline to the crown. The rise to run ratio is 28 percent. The spandrel walls are approximately 4 feet by 12 feet. The wingwalls are approximately 5 feet by 4 feet. There is a clear roadway width of 15 feet, with an overall bridge width of 17 feet 4 inches. The spandrel walls have moderate deterioration and small areas of patching. According to a 1997 inspection report the bridge is in satisfactory condition with a sufficiency rating of 54.4.

The builders used a closed parapet design that consists of vertical posts securely fastened by dowels to the structure, horizontal rails, and solid panels that fill the space between posts and the railings. The panels may be precast, and the posts and rails were built in place. The precast panels are separated by solid paneled expansion joints. A 4-inch by 6-inch ledge extends the length of the parapets on the exterior of the bridge. The parapet wall is 20 feet with 4 incised panels within the wall. Each incision is 4 feet by 1 foot.

## **Discuss Major Alterations:**

No alteration have been made to this structure.

When Built: circa 1920

Why Built: Improvement of lateral corridors

Who Built: Unknown Who Designed: Unknown

Why Altered: N/A

Was this bridge built as part of an organized bridge building campaign? No, this bridge was not built during an organized bridge building campaign.

#### Surveyor Analysis:

This bridge may have NR significance for association with:

XA Events Person XC Engineering/Architectural

This bridge was determined eligible by the Interagency Review Committee in March 1996.

## Was this bridge constructed in response to significant events in Maryland or local history?

In 1920 the Maryland State Legislature enacted the "Lateral and Post Roads Loan of 1920." The act that created this loan provided that the proceeds were to be used for the construction of rural post roads, lateral roads and the extension of the State Roads System, with the assistance of funds from the federal government and several counties in the State. Half of the loan was used for the purpose construction of lateral roads. This money was apportioned to the counties on the basis of actual road mileage. The counties then matched the State's money with bond issues, special assessments, or other revenue.

Is the bridge located in an area that may be eligible for historic designation and would the bridge add to or detract from historic and visual character of the possible district?

No, this bridge is not located in an area that is eligible for historic designation.

# Is the bridge a significant example of its type?

Yes, this bridge is a significant example of its type. The bridge has a low rise to run ratio which is characteristic of the Luten style of construction. However the bridge can not officially be attributed to Luten.

Does the bridge retain integrity of the important elements described in the Context Addendum?

This bridge retains integrity of all of the character defining elements of a concrete arch.

Should this bridge be given further study before significance analysis is made and why?

No this bridge should not be given further study.

Bibliography:

County inspection/bridge files \_\_\_\_\_ SHA inspection/bridge files \_\_\_\_\_


Other (list):

**Surveyor:** 

Name: Stacie Y. Webb Date: March 1996

Organization: State Highway Admin. Telephone: (410) 545-8559

Address: 707 N. Calvert Street, Baltimore, Maryland Edited by P.A.C. Spero & Company, December 1997





Inventory	#	M:	2	3-	133

M C 80
Name M120-GRIFFITH OVER HAWLINGS BIVER
County/State Montoomery mo
Name of Photographer FRANK JULIANO
Date 2 95
•
Location of Negative SHA
Description Approach WEST
Number Z of 38



Inventory	#	M:	23	-133
-----------	---	----	----	------

Name MIZO-GRIFFITH RO OVER HAWLINGS RIVER
County/State Montoomery mo
Name of Photographer FRANK JUMANO
Date 2/95
Location of Negative SHA
Description ELEVATION SOUTH
Number of 38



# Inventory # <u>M: 23 - /3</u>3

Name MIZO-GRIFFITH ROOMER Hawkings RIVER
County/State Montgomery mo
Name of Photographer FRANK JULIANO
Date 295
•
Location of Negative SHR
Description APPROACH EAST
0
3 4
Number 4 of 33



# Inventory # <u>M: 23-133</u>

Name M120-GRIFFITH RD OVER HAWLINGS RIVER  County/State Montgomery mo  Name of Photographer FRANK JULIANO  Date 295
Location of Negative SHA
Description ELEVATION NORTH
Number of 3/3